No. 699

August 16, 1976

Replaces No. 693 dated July 23, 1975

CARBURETOR MODIFICATION/SX-250, SS-175

SX-250

In certain geographical locations an over-rich carburetion condition (four-cycling) may exist in the RPM midrange of early 1975 Model SX-250 motorcycles, leading to poor performance and premature carbon buildup and restriction in the exhaust system.

Therefore, if this condition is encountered, we recommend the following carburetor changes for performance improvement.

Replace old parts with new parts shown in table below.

<u>Item</u>	New Part Number	(Replaces)	Old Part Number
Low Speed Jet	27610-75P (50)		27617-65P (55)
Main Nozzle	27791-75P (AB260)		27778-74P (AB265)
Metering Pin	27790-75P (K9)		27777-74P (K4)

Identification of components, shown in parenthesis after part numbers, are stamped on the parts.

Carburetors on later 1975 SX-250 motorcycles will incorporate the above changes.

SS-175

The following carburetor changes are recommended to improve performance for 1976 SS-175 motorcycles which have an over-rich carburetor condition. New parts replace the old parts as shown in the table below.

For convenience in ordering, a special kit consisting of new parts required for one motorcycle is available under part No. 93189.

<u>Item</u>	New Part Number	(Replaces)	Old Part Number	
Low Speed Jet High Speed Jet Metering Pin Main Nozzle Throttle Slide	27606-69P (60) 27694-69P (100) 27801-75P (V10) 27803-75P (260P) 27802-75P (70)		27617-65P 27676-76P 27081-74P 27532-75P 27702-69P	(105) (V3) (265P)

Identification of components, shown in parenthesis after part numbers, are stamped on the parts.