August 16, 1977

PISTON PIN RETAINING RINGS / 1000CC & 1200CC MODELS

1200 and 1000 cc models now incorporate Truarc type retaining ring with holes for Truarc Pliers (our part No. 96215-49). The groove in the piston pin bore has been changed to accommodate the new piston pin retaining ring, part No. 22588-78, which replaces the Spirolox retaining ring, part No. 22582-52. The new ring is easier to install in the groove, lessening the possibility of incomplete register in the groove which could allow the ring to come out during engine operation. The new ring must be used on new pistons only, since it will not fit correctly in old pistons (It will be loose and may come out during service). All replacement piston and ring sets will have new part numbers as listed below.

All parts order pistons with new part numbers as listed below and pistons assembled in engines starting June 10, 1977 have the new lock ring and are identified with a stamped number "7" or "77" on the top of the piston.

After piston castings are changed, the pistons will no longer be stamped on the top, but will have a " 77 " cast into the metal inside the piston for identification.

1200cc 1000cc 1200cc Low Compression High Compression STD 22251-72A 22101-74A 22141-74A .010 22253-72A 22103-74A 22143-74A 22144-74A .020 22254-72A 22104-74A 22255-72A 22105-74A 22145-74A .030 22256-73A 22106-74A 22146-74A .040 22107-74A 22147-74A .050 22257-73A 22108-74A 22148-74A .060 22258-73A 22259-73A 22109-74A 22149-74A .070

PISTON AND RING SETS

CAUTION: Do not use the new Truarc retaining ring in early pistons-It will fit too loose. Use it only in late pistons marked with the number "7" or "77".

HARLEY-DAVIDSON MOTOR CO., INC.

-																
	ROUTING	SERVICE	SALES	PARTS	CHIEF	MECHANIC MECHAN		IANIC	MECHANIC		MECHANIC		RETURN			
		MANAGER	MANAGER	MANAGER	MECHANIC	NO. 1		NO.	2	NO.	3	NO.	4	THIS	TO:	
ı	INITIAL															
-	HERE-				Ï					i				l		