



2020-03-23

[illegible]

States notifying them of this safety-related condition and instructing them to contact their dealer for inspection and service. A sample of the customer letter is attached. Harley-Davidson Canada will send a letter to registered owners of affected product in Canada. Other customers outside the United States may receive this notification by other means.

To protect the safety of our riders, it is our mutual responsibility to ensure the recall service is performed on all affected motorcycles. Therefore, we strongly urge you to perform the recall service even if the motorcycle was not purchased from your dealership. You are also required to perform the recall service on all affected models in your dealership inventory prior to delivering, renting or leasing those models.

NOTE

Because only registered owners will receive notification from us, we request that you contact any owners of affected motorcycles still listed as unregistered. Advise them of the safety recall and make arrangements for them to come in for recall service. We also require that you provide us with their names, addresses and VINs as soon as possible to enable us to mail them an owner's letter, as required by the National Traffic and Motor Vehicle Safety Act (as amended).

Ordering Information: U.S. and Canada

Dealers (U.S. and Canada) may order recall kits (Part No. 91500085) by following the instructions on the attached order form.

NOTE

For each kit ordered you must provide a VIN of the motorcycle on which the kit will be installed. Orders without VINs, or that exceed the maximum quantity of two, will become invalid and will not be processed. Kits have limited availability, do not order to build inventory.

Table 2. Safety Recall Code [0167] Kit (Part No. 91500085) Contents

ITEM	PART NO.	QTY
Clamp	10038A	1
Locknut	10100013	10
Clamp	70345-84	1
Fuel Line	61200024	1
Fuel Pump	61200001A ⁽¹⁾	1
	With cable strap ⁽¹⁾	
	61200001B ⁽²⁾	
	Without cable strap ⁽²⁾	
Vent baffle	61100046A	1

(1) Do not remove cable strap.
(2) Does not need cable strap.

Ordering Information: Non-U.S. Market

Contact your local Harley-Davidson service area representative for authorization, ordering and return instructions.

Asia Pacific

Contact your service and customization consultant.

Canada

Canada will follow the U.S. ordering process.

Europe

Follow standard H-Dnet order process. In case of questions or concerns, contact your local PAM (Parts, Accessories and Motorclothes) representative.

India

Contact your service and customization consultant.

Mexico

Contact the local service area representative at Harley-Davidson Mexico.

Japan

Contact the local service department at HDJ.

Required Dealer Action

1. Verify that the motorcycle is involved in this recall.
2. Replace the fuel pump. See the service manual. Refer to Fuel Pumps.
3. Remove the fuel tank cap.

NOTE

When removing and installing the vent baffle, cover fuel tank inlet to prevent vent baffle from falling into fuel tank.

4. See Figure 1. Remove the vent baffle (3) from the filler neck (2).
5. Install the **new** vent baffle.
6. Install the fuel tank cap.

Upon completion of the recall, follow the instructions listed under the appropriate Credit Procedure. Submit recall claims promptly.




Figure 1. Vent Baffle

Fuel Pumps

Recall kit (Part No. 91500085) may contain two different fuel pumps which both work:

- See Figure 2. **61200001A**: This fuel pump is designed with a cable strap (1) installed on the pump, do not remove.




Figure 2. Fuel Pump - 61200001A

- See Figure 3. **61200001B**: This fuel pump is designed without a cable strap (1) installed on the pump, cable strap is not need. The part number is etched (3) on updated fuel pump.




Figure 3. Fuel Pump - 61200001B

Credit Procedure: Talon/h-dnet.com Warranty Claim System Users

For each motorcycle involved in this recall (involvement of VIN has been verified on h-dnet.com), submit a recall claim per the applicable table below.

Table 3. Talon/h-dnet.com Warranty Claim System Users

ITEM	DATA
Claim Type	SRC
Problem Part Number	61200001
Quantity	Leave blank
Primary Labor Code*	3570
Time**	1.0 hours
Customer Concern Code*	0167

Table 3. Talon/h-dnet.com Warranty Claim System Users

ITEM	DATA
Condition Code	9981
Replacement Part Number	91500085
Quantity	1
* These items may need to be downloaded to your system.	
** Labor time includes time coverage for fuel drainage and replacement.	

Credit Procedure: SAP System Users

For each motorcycle involved in this recall (involvement of VIN has been verified on h-dnet.com), submit a recall claim per the applicable table below.

Table 4. SAP System Users

ITEM	DATA
Claim Type	Recall Claim
FIX ID-Found in Recall Number	C
Problem Part Number	61200001
Customer Concern Code	0167
Condition Code	9981

Credit Procedure: All Other System Users

- Claim Date
- Campaign Number (0167 (labor time 1.0 hour)
- Fix ID (C)
- Full seventeen character VIN

Upon submission of the properly completed recall claim, you will be credited for labor for performing the safety recall procedure plus appropriate market administrative time. The safety recall record will be updated. Each recall completion must be filed on an individual claim. Do not submit additional warranty events on these claims.

Table 5. Talon/h-dnet.com and other Non-SAP system Users Dealer Stock Inventory Parts

ITEM	DATA
Claim Type	SNV
Problem Part Number	61200001
Quantity	Will Vary
Customer Concern Code*	0167
Condition Code	9982
* These items may need to be downloaded to your system.	

Table 6. SAP System Users Dealer Stock Inventory Parts

ITEM	DATA
Claim Type	PAM-Stock
Problem Part Number	61200001
Quantity	Will Vary
Customer Concern Code	0167
Condition Code	9982

Part Return Information: All Markets, All Tables

Hold all replacement parts for 60 days from date of credit issue for possible field inspection and/or return to factory. After 60 days, destroy and discard parts.