



## Boom! Related P&A Kit Bulletins

- PAB1001: Boom! Box Audio System - Out of Warranty Repair Process
- PAB1006: Boom! Amplifier Software Update
- PAB1012: Boom! Audio Bike-to-Bike Communications (CB) Kit Additional Requirements

## Software Update (1.21.0.4): Boom! Box 4.3/6.5GT/6.5 CVO GT

### Fixes

- Intermittent software lock up caused by long text strings in lists
- Traffic settings missing from setup menu for HDI software
- Intermittent loss of audio and voice recognition after prompt
- Siri® not launching consistently if voice recognition is activated
- Software freeze with intermittent USB cable operation
- POI searches "near destination" was searching near current position

## Software Update (1.21.2.1): Boom! Box 4.3/6.5GT/6.5 CVO GT (Release date 07-31-2017)

### Improvements

- Notice stating that "Some models are susceptible to damage from vibration. Refer to the user manual" has been updated to clarify that it applies to some older media devices when plugged into the USB (Universal serial bus) port. New notice will now state "Some media devices are susceptible to damage from vibration. Refer to the user manual".

### Fixes

- Siri operation fixes.
  - a. Siri not initiating in some instances with long press of VR (Voice recognition) button.
  - b. VR canceling Siri initiation despite activation through button press.
  - c. VR initializes before Siri initiation.
- Global presets from USB device grayed out in display despite USB device plugged in.
- Global presets are highlighted even after USB device is removed.
- Scroll down button selects last item in media list in some instances.
- Squelch pop up not shown properly in all instances after squelch button activation.
- Map database names in some international regions were not fully displayed.
- Next turn shown on weather map in some instances.
- Various bug fixes.

## Software Update (1.21.3.1): Boom! Box 4.3/6.5GT/6.5 CVO GT (Release date 09-18-2017)

### Fixes

- Radio software stuck in reboot loop during map database update, intercontinental replacement or intercontinental restoration process.
- Radio software freezing and lockup during dealer location database updates.