September 10, 2001



ENGINE SPROCKET NUT

Purpose

B-043

The purpose of this bulletin is to notify dealers that some Buell motorcycles were produced with incorrectly manufactured engine sprocket nuts. The incorrectly manufactured nut has an interference fit which may result in a false torque reading. This can cause the nut to lose clamp load on the engine sprocket, allowing the sprocket and alternator rotor to loosen and create noise.

Motorcycles Affected

Late production 2000 and early production 2001 (5/15/2000-6/15/2000) Buell X1, M2, S3 and P3.

Required Dealer Action

In the event that a customer complains of an unusual noise, start the motorcycle and inspect for a noise in the primary housing. If any unusual noise is heard in the primary housing, shut the motorcycle off, remove the primary cover and inspect the engine sprocket nut.

NOTE

See the applicable service manual for primary cover removal and replacement procedure.

See Figure 1. A good, serviceable sprocket nut is shown on the left side of the figure. An incorrectly manufactured nut is shown on the right, identified by two arrow-shaped indentations on the face of the nut.

NOTE

If an affected motorcycle has been brought in for repair and the primary cover is removed, inspect the engine sprocket nut. Replace if it is determined to be an incorrectly manufactured nut.




Figure 1. Engine Sprocket Nut

ROUTING	SERVICE	SALES	PARTS	LEAD	TECHNICIAN	TECHNICIAN	TECHNICIAN	TECHNICIAN	RETURN
	MANAGER	MANAGER	MANAGER	TECHNICIAN	NO. 1	NO. 2	NO. 3	NO. 4	THIS TO:
INITIAL HERE									

Credit Procedure

After servicing each vehicle, file a warranty claim referencing Service Bulletin B-043 in the "Description of Repair" or "Comments" section of the claim. Fill in the rest of the claim as follows:

Claim Type	BMC, BGW*			
Event 1	Qty 1	Problem Part No. 7839		
Part Description	Engine Sprocket Nut			
Primary Labor Code	4003			
Time:	0.8 hr.			
Customer Concern Code	4104			
Condition Code	3203			

^{*}Use BMC if vehicle is still within factory warranty period; use BGW if vehicle is beyond factory warranty period. Vehicles beyond factory warranty period do not require prior authorization. If using h-dnet.com, put "Per Bulletin B-043 in the authorization box.

©2001 Buell Distribution Corporation

B-043 1 of 1