

Parts & Accessories Bulletin

May 2, 1994



PAB #520

1994 CATALOG CORRECTIONS

This bulletin is an update to the 1994 Genuine Accessories, Eagle Iron, and Chrome Hardware Catalogs. We have recognized some minor errors in the catalogs and wanted to communicate the correct information. Please route this bulletin throughout the various departments within your dealership who use the P&A Catalogs as a sales tool, etc.

1994 GENUINE ACCESSORIES CATALOG

Fitment Corrections:

Page 47, Item G, Heritage Chrome Front Fender Rail, P/N 91080-93, fitment is incorrect. The correct fitment is '87-'94 FLST, FLSTC and FLSTN models.

Page 58, Item H, Swingarm Pivot Cover, P/N 43897-86B, fitment is incorrect. The correct fitment is '84-'94 Softail models.

Page 65, Item F, Dresser V-Logo Front Fender Rail, P/N 91099-94, fitment is incorrect. The correct fitment is '80-'94 FLT, FLHT, FLHS, FLHR models.

Page 71, Item L, Chrome License Plate/Light Kit, P/N 68230-88B, fitment is incorrect. The correct fitment is '86-'93 FLHS models and '86-'94 FLT, FLHT models.

Page 100, Item A, #2, Genuine Handlebars, P/N 55934-92, fitment is incorrect. The correct fitment is '92-'94 models.

Pricing Corrections:

Page 10, Item E, Low Suspension Fork Kit, P/N 45480-94, price is incorrect. The correct price is \$149.95.

Page 59, Item J, Chrome Rear Directional Mounting Bar, P/N 68510-74B, price is incorrect. The correct price is \$61.90.

Part Number Corrections:

Page 16, Item D, XL King/Queen Seat, P/N 52146-83B is incorrect. The correct P/N is 52146-83A.

Page 53, Item I, Right Side Chrome Tool Box, P/N 64201-85C and Item J, Left Side Chrome Tool Box, P/N 64207-89B are incorrect. The correct P/N's are 64201-85B (Right) and 64207-89A (Left).

Page 57, (Item not shown - listed under item H) FLST Fat Boy Directional Extension Kit, P/N 53491-92B is incorrect. The correct P/N is 53491-92.

Page 65, Item H, Dresser V-Logo Rear Fender Rail, P/N 91109-94 is incorrect. The correct P/N is 91100-94.

NOTE: All Part Number corrections have been accounted for in H-D's order entry system. Thus, even if you place an order for the incorrect P/N as listed in our catalog, the order will automatically be "superceded" to the correct P/N.

(OVER)



FILE IN ACCESSORY GUIDE FOR FUTURE REFERENCE

Miscellaneous Changes:

Page 58, Item E, Softail Dual Fishtail Exhaust, P/N 65281-92A, the description should include: "On '92 and earlier will need to purchase a shifter rod separately".

Page 70, Item B, Left Side Cover Trim Rail, P/N 66053-92 is missing from the catalog text, but is shown in box B. The fitment for this part is: Fits '81-'92 FLTC, FLHTC, and FLHS models (does not fit '93-'94 models).

Page 80, Item D, King Tour-Pak Brake/Taillamp Kit, P/N 68012-88B, display photo is incorrect. The taillamp kit is manufactured with only one antenna, not two as shown in the photo.

Page 90, Item F, 1-piece Black Solo Seat and Pillion, P/N 52498-85 is obsolete. That product is no longer available.

Page 94, Item A, There are no part numbers listed for tall or low uprights for "All FXSTC, FXSTS models". The part numbers for the uprights are the same as the FXWG uprights listed in the row above in the table in the catalog:

<u>Tall uprights:</u>	53552-81	Insert Style
	52749-85	Medallion Plate Style
<u>Low uprights:</u>	52736-85	Insert Style
	52735-85	Medallion Plate Style

Page 110, Item A, Dunlop Tires, Pictures #1 and #3 are of the wrong tires. The P/N's and fitments are correct, but the photos are not.

Page 116, Item B, the heading is incorrect. Under the heading, "**XL Chrome Voltage Regulators**" both XL and 1340 Big Twin voltage regulators are listed. The part numbers and fitments are correct.

1994 EAGLE IRON CATALOG

Page 30-31, Items 4 and 9, descriptions are incorrect. Item 4 is a Dyna Wide Glide Handlebar, P/N 56079-93T and Item 9 is a Buckhorn Handlebar, P/N 56081-82T. The descriptions were inadvertently flipped.

Page 62, Item H, Blue Buster Polishing Kit, does not have a part number listed. The correct part number is 99835-94T.

1994 CHROME HARDWARE CATALOG

Inside flap, Item A, Chrome Screw Kit for FLST Seat Bracket, P/N 24239-93T is incorrect. The correct part number is 24289-94T.

Inside flap, Item B, Smooth Head Hardware Kit, P/N 94291-93TS is incorrect. The correct part number is 94291-94TS.