



Tech Article

TA0021: Front Wheel Skid Spacer for 2018 Touring

Reference	TA0021
Last Modified	2017-08-31
Models	2018: FLHP, FLHR, FLHRC, FLHRXS, FLHTCU, FLHTK, FLHTK ANV, FLHTK SHRINE, FLHTKL, FLHTKSE, FLHTKSE ANV, FLHTP, FLHX, FLHX ANV, FLHXS, FLHXS ANX, FLHXSE, FLTRU, FLTRX, FLTRXS, FLTRXSE
Category	Chassis
Markets	U.S. market is affected.
Vehicles Affected	2018 Touring, CVO Touring and Police
Symptoms	Front fender damage caused by shipping spacer.

Description

See Figure 1. A spacer was added to the shipping skid for the front tire of 2018 Touring, CVO Touring and Touring Police vehicles. The spacer is used to chock the tire in the skid correctly. This avoids shipping strap contact and possible damage to the front fender.

The spacer can remain attached to the front tire. This may damage the front fender as the motorcycle is removed from the skid.

Action

See Figure 2. When removing the motorcycle from the skid, verify that the spacer separates from the front tire. If spacer remains attached, remove spacer before it contacts the front fender.

1124375



Figure 1. Front Wheel Skid Spacer

1124330



Figure 2. Removing Front Wheel Skid Spacer