

SERVICE BULLETIN



M-1108

Noncompliance Recall Code 0600, 0601 0602

April 2, 2001

2001 SPORTSTER EMISSION CONTROL LABEL

General

Harley-Davidson has determined that certain 2001 SPORTSTER model motorcycles were manufactured with the incorrect Vehicle Emission Control Information label.

In the interest of United States Environmental Protection Agency (EPA) regulatory compliance, Harley-Davidson has elected to initiate a voluntary noncompliance recall campaign.

Owners of affected vehicles will receive the correct Emission Control Label for their vehicle. They will also receive an instruction sheet (J01326) and letter detailing the recall.

Dealer Action-Affected Vehicles

To determine if you have an affected vehicle in your dealer inventory, you can contact the recall information line at 1-800-448-1708 or check on TALON and h-dnet.com. To obtain the appropriate replacement label, send a fax to the attention of Danielle Fina at 414-343-8346. Your fax **must include** your dealer number, the VIN (Vehicle Identification Number) of the affected motorcycle in your inventory and the appropriate recall number (Service Code.) Refer to Table 1 for vehicle/recall identification. Labels will be sent via U.S. mail only for affected units and only upon request.

Dealer Action-Registered Units

Owners of affected vehicles will receive an instruction sheet on how to affix the label themselves. However, customers not comfortable with installing the label will be instructed to contact their local Harley-Davidson dealer for installation.

Instructions

See Instruction Sheet J01326 for installation procedure.

Credit Procedure

For each vehicle your dealership has remedied, fill out a Dealer Service Card. Be sure to list the appropriate recall (service code) number on the card. See Table 1. Place a "C" in the letter box. When Harley-Davidson receives your properly completed Dealer Service Card, you will be credited 0.2 hours of labor for performing the procedure, which includes 0.1 hour for administration time.

Table 1 Vehicle Identification

RECALL NUMBER	MODEL AFFECTED
0600	1200 Sport (CHP)
0601	1200 (CAP) 1200 Custom (CGP)
0602	883 (CAM) 883 Hugger (CEM) 883 Custom (CJM)

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	LEAD TECHNI- CIAN	TECHNI- CIAN NO. 1	TECHNI- CIAN NO. 2	TECHNI- CIAN NO. 3	TECHNI- CIAN NO. 4	RETURN THIS TO:
INITIAL HERE									