

April 05, 2004

Left Rear Speaker Box

All Ultra style left speaker boxes have a slit in the underside of the vinyl fabric. This slit marks the hole for the headset tether bracket screw. The slit is not a defect and the speaker box should not be replaced. Instruction sheets for all kits that use this speaker box are being changed and will point this out to the installer.