

May 31, 2004

Labor Code Information

We are making a change to labor code 6509 for 2004 FCW/FLW/FGW models. The time is changing from 2.6 hours to 1.4 hours. Ultra tourpaks have been available with the lights already installed for quite some time so replacement time is reduced. Make this change to your Job Time/Code Manual on page 3 -14.

REMINDER:

Job/Time codes can be updated from time to time. If you attempt to use a labor code listed in the current Job/Time code manual and your computer won't access that code, please download your labor codes from the Talon or Lightspeed warranty systems before calling the warranty department. We communicate weekly with Talon and Lightspeed on updates and the issue may have already been resolved.

If you use hdnet.com or have downloaded from Talon or Lightspeed and the labor code will still not work for you, please call the Warranty department for assistance.