

April 25, 2005

XL Model Rear Fenders

As of March 2, 2005 the XL rear fenders no longer have the protective tape, part # 59547-04, between the fender and seat pan. It was found through testing that with the improved seat pan it was no longer required. Please do not file a warranty claim for missing protective tape on these vehicles.