

June 6, 2005

Labor Code 4332

Labor code 4332 for 2004-2005 Sportster Models is incorrect in the Flat Rate Manuals. Please change your manuals for this code from 11.3 hrs. to 1.3 hrs. This code can be found under the Transmission table and is: Replace shift linkage and/or spring – includes pawl adjustment.