

Tech Tip # 59 (All 2005 Items)

January 4, 2005 - Horn Issues	2
January 10, 2005 - Twin Cam Valve Spring and Camshaft Information	3
January 17, 2005 - Screamin' Eagle® Pro EFI Race Tuner	4
January 24, 2005 - H-D Pre-Delivery and Setup Manual	5
January 31, 2005 - Springer Softail Labor Code Update	6
February 7, 2005 - 2006 VRSCR Front Tire	7
February 15, 2005 - ECM Connector	8
February 21, 2005 - 2004/2005 V-Rod Leak Detection Process	9
February 28, 2005 - VRSCR Front Fork Oil Level Correction	10
March 7, 2005 - Warranty News and Updates	11
March 16, 2005 - Service Bulletin M-1162	12
March 22, 2005 - Twin Cam Piston Identification Markings	13
March 28, 2005 - Owner's Manual Corrections: 2005 VRSCSE	14
April 4, 2005 - Softail Flywheel Balancer Sprocket	15
April 11, 2005 - Recall 0118 Clarification	16
April 18, 2005 - 2005 FLT Police Model Parts Catalog	17
April 25, 2005 - XL Model Rear Fenders	20
May 2, 2005 - Bulletins M-1089A & PAB844	21
May 9, 2005 - 2005 XL Model Wire Harness Elbow	22
May 16, 2005 - CVO Tour-Pak Interior Light Kits	23
May 25, 2005 - Screamin' Eagle Stage I & II Kits	24
May 31, 2005 - Screamin' Eagle® Pro EFI Race Tuner	26
June 6, 2005 - Labor Code 4332	27
June 13, 2005 - Fuse Part Number Quick Reference Guide	28
June 21, 2005 - Front Brake Light Switch Installation Procedure	29
June 27, 2005 - Screamin' Eagle 6-Speed Transmission Speed Sensor Plugs	30
July 5, 2005 - 2006 VRSCR Service Manual Correction	31
July 5, 2005 - ECM Running Change	33
July 13, 2005 - PDI Recommendation	34
July 19, 2005 - Cruise Control Set/Resume Switch	35
July 25, 2005 - 2006 Calibrations	36
August 3, 2005 - 2006 Model Year Information	37
August 3, 2005 - 2006 Fuse Block Covers	38
August 10, 2005 - Diagnosing Oil Consumption	39
TT208 - August 15, 2005 - Stage Downloads	42
TT209 - August 22, 2005 - Advanced Audio System Information	43
TT210 - September 13, 2005 - 2006 Fairing Equipped Touring Model Ignition Switches	44
TT211 - September 16, 2005 - Sportster and Buell XB Model Flywheel Sprocket Shaft Nut Torque Update	45
TT212 - September 21, 2005 - 2006 Dyna Model Primary Drive Locking Tool	46
TT213 - September 26, 2005 - VRSCSE2 & VRSCR Model Ignition Switch Covers	47
TT214 - October 3, 2005 - XL Stator plug connector	48
TT215 - October 10, 2005 - EFI Heat Management Strategy	49
TT216 - October 17, 2005 - Leather/Vinyl Products Repair Information	50
TT217 - October 24, 2005 - Instructions for setting V-Rod Model clocks	57
TT218 - October 31, 2005 - 2006 Dyna Model Wire Harness	59
TT219 - November 07, 2005 - Diagnostic Trouble Code Information	60
TT220 - November 14, 2005 - Service Bulletin M-1180 Correction	61
TT221 - November 28, 2005 - 2006 HDI Dyna Model O2 Sensor Plugs	62
TT222 - December 5, 2005 - Engine Remanufacturing Updates	63
TT223 - December 6, 2005 - Service Bulletin M-1180 Correction	64
TT224 - December 12, 2005 - TSSM Enhancements	65
TT225 - December 19, 2005 - 2006 PDI Manual	66
TT226 - December 23, 2005 - Holiday Shutdown	69