

TT364 – February 27, 2008 - VRSC Auxiliary Volume Exhaust Shield Mounting  
**VRSC Auxiliary Volume Exhaust Shield Mounting Fastener Orientation**

If for any reason, AV exhaust shields or AV exhaust shield fasteners were removed from exhaust system, they must be replaced with **new** fasteners and tightened properly. Failure to do so can result in the heat shield coming loose

Torque specifications are 10Nm (8.8 in lb)

Exhaust shield nuts part number 8070M have to be oriented a certain way to function properly, chamfer side should face out.

