



TT401: XL Mirror Stem Protective Cap

March 25, 2009



Chassis

APPLIES TO	SYMPTOMS
2009 Sportster models	<ul style="list-style-type: none">• Part Availability, Installation or Fitment Updates• Literature Updates or Corrections

Tech Tip 401

Recently, Harley-Davidson has changed the installation procedure for the mirrors on XL models. The protective cap, part number 8908, which was installed on the mirror stem threads is no longer required and has been eliminated. A new, taller locknut, (part number 7725) which provides additional thread engagement, eliminates the need for the protective cap.

NOTE

Return Material Authorization (RMA) claim requests will no longer be accepted for this part as being missing from the vehicle.




Figure 1. XL Mirror Stem (protective cap removed)

Please update the 2009 Sportster Model PDI manual to reflect that NO protective cap is required. The "HEADLAMP & MIRROR" section of the 2009 Sportster Parts Catalog should also be corrected to reflect the running change.