



TT462: TEAR-AWAY CABLE STRAP

2017-11-15



Other
Category

APPLIES TO	SYMPTOMS
Softail and Touring	<ul style="list-style-type: none">• PDI (Predelivery inspection)

Reason for Tech Tip

The assembly plants are trying a **new** tear-away cable strap.

Issue

Damage has occurred on some hand grips or brake levers when using side cutters to cut the cable strap that holds the keys in place.

Resolution

1. Refer to Figure 1. Remove tear-away cable strap.
 - a. Grasp tail (1) of cable strap with one hand.
 - b. Grasp tear-away tab (2) with other hand.
 - c. Pull tab to release. Refer to Section Video.


Video

NOTE

Login into SIP (Service information portal) through Google Chrome to view video.

Click on link to view video of the removal of the tear-away cable strap.

https://serviceinfo.harley-davidson.com/sip/service/document/index?reference=TT462VIDEO&locale=en_US



1. Tail

2. Tear-away tab

Figure 1. Tear-Away Cable Strap