## **Table of Contents**

1: Oiling & Lubrication - Sub-04E		
Pics and Information on 1957-1978 XL, XLH "Kidney" Oil Tanks	3	
1957-1966	3	
1967-1978	4	
Oil Cap	5	
Rebuilding the Kidney Tank Oil Cap		

tections in torone mayor with spot back period. Unfillular priprectifials. In torone mayor with spot back period. Unfillular priprectifials. In torone mayor with spot back period. Unfillular priprectifials. In the spot period. The spot period of the spot period. The spot period of the spot period of the spot period of the spot period. The spot period of	Last update: 2024/01/01 20:45	techtalk:ih:oil04e https://www.sportsterpedia.com/doku.php/techtalk:ih:oil04e
	Last update. 2024/01/01 20.43	techtaik.iii.oiio4e https://www.sportsterpedia.com/doku.php/techtaik.iii.oiio4e

Go To Technical Menu

# IH: Oiling & Lubrication - Sub-04E

# Pics and Information on 1957-1978 XL, XLH "Kidney" Oil Tanks

See also in the Sportsterpedia;

..... \*57-85 Oil Line Routing

..... \*Pics and Information on stock IH Battery Trays and Parts

Click on any pic below to enlarge:

## 1957-1966

1957-1966 tanks had a separate bracket (47371-52) to attach it to the frame.











## 1967-1978

From 1967-1978, the bracket was spot welded to the tank.









# Oil Cap

There have been negative comments about in-tank oil filters in the past, but these all refer to an old, original "horse hair" filter.  $^{10}$ 

The modern replacements are very good indeed.

But you'll need to shorten your dipstick to use the newer in-tank filters unless you find a "Horsehair" type. 11)

The newer pleated paper ones are a better choice though.

See the example below of shortening the dipstick.



### Rebuilding the Kidney Tank Oil Cap

These pics show how the oil cap comes apart.


Here is what you have when you flip it over and clean it up.

With the C-clip removed, hold the round end that the dipstick comes out of.

Turn the wing nut counter clockwise to unscrew it from the rest of the assembly.

The lower section will slide to the side and then lift out one side at a time.

This is not necessary to replace the gasket or the O-ring but it may be for something more in depth.



There is an O-ring at the top of the shaft between the cap and the wing nut. If it's flattened, it may cause an oil leak on the top of my tank.



#### Go To Technical Menu

1) 2) 3) 4) 5)

photo by Magneto Sportster of the XLFORUM

https://www.xlforum.net/forum/sportster-motorcycle-forum/sportster-motorcycle-era-specific-and-model-specific/ironhead-sportster-motorcycle-talk-1957-1985/198705-magneto-sportster-s-1964-xlh-restoration-project/page4?t=2075542&page=4

6) 7) 8) 9)

photo courtesy of Ebay seller, rusty\_dusty\_parts, store: Ebay store link:

#### IronMick of the XLFORUM

https://www.xlforum.net/forum/sportster-motorcycle-forum/sportster-motorcycle-era-specific-and-model-specific/ironhead-sportster-motorcycle-talk-1957-1985/195757-in-tank-oil-filter?t=2072162

#### Popgadget of the XLFORUM

https://www.xlforum.net/forum/sportster-motorcycle-forum/sportster-motorcycle-era-specific-and-model-specific/ironhead-sportster-motorcycle-talk-1957-1985/195757-in-tank-oil-filter?t=2072162

From:

https://www.sportsterpedia.com/ - Sportsterpedia

Permanent link:

https://www.sportsterpedia.com/doku.php/techtalk:ih:oil04e

Last update: 2024/01/01 20:45

