

CHECK TIGHTNESS OF CYLINDER BASE NUTS

Check tightness of all cylinder base nuts on ELECTRA GLIDE, SPORTSTER AND SERVI-CAR motorcycles when received from the factory before motorcycle is put into operation. This is necessary because there is some loss of tightness due to gasket set and metal stretch occurring during initial engine run-in at the factory. If nuts are allowed to loosen further in service, cylinders will probably crack at the base. Therefore, it is very important that tightness of cylinder base nuts on all motorcycles (including those previously delivered to customers) be checked as soon as possible.

HARLEY-DAVIDSON MOTOR CO.