

# **SERVICE BULLETIN**

No. 574

July 12, 1968

## **EXHAUST PORT GASKET SEAL — ELECTRA GLIDE**

Starting on May 27, 1968 with engine serial No. 68FLH 14610, an asbestos gasket ring is assembled in the exhaust port-to-pipe joint to prevent exhaust leakage. Also, a chamfer has been incorporated on the exhaust port I.D. to provide a recess for the seal ring. The gasket, part No. 65834-68, can be used on earlier cylinder heads not having a chamfer in the exhaust ports, if care is used when tightening the exhaust pipe flange bolts so that they are drawn up evenly to prevent cocking.