

No. 590A

August 24, 1970

Replaces No. 590 dated June 17, 1969

GENERATOR ARMATURE AND SHAFT / SPRINT

Starting with Serial No. 69SS 3672 all 1969 Sprint engines have a larger armature shaft taper. The taper diameter has been enlarged approximately 1/8 in. at same taper angle as old one for increased strength.

Replacement generator armature and crankshaft part numbers applying to these late 1969 engines are shown below.

<u>New Part No.</u>	<u>Name</u>	<u>Replaces Old Part No.</u>
30855-70P	Armature	30855-62P
23707-69P	Flywheel Assy.	23706-69P
23712-69P	Flywheel, Left	23710-69P

Note: Old flywheel assembly 23706-69P will no longer be supplied for parts order, being replaced by 23707-69P. Therefore, when ordering new flywheel assembly for engine serial numbers below 69SS 3672, a new armature part No. 30855-70P must be ordered separately.

HARLEY-DAVIDSON MOTOR CO., INC.