

SERVICE BULLETIN

M-1017

October 4, 1991



BRAKE LAMP RELAY KIT

General

This is an informational Service Bulletin to call Dealers' attention to the Brake Lamp Relay Kit (Part No. 77043-91) designed for installation on 1990 and earlier FLT/FLHT Ultra models.

On 1990 and earlier FLT/FLHT Ultra models, which were not originally equipped with a brake lamp relay circuit, certain electrical difficulties may arise (i.e. - the rear stop lamp switch can fail, and the rider may experience a "popping" noise in the sound system speakers when the brakes are applied).

In 1991, Harley-Davidson added a relay circuit to the original brake lamp electrical circuit in order to eliminate the previous electrical difficulties.

If any of your customers' 1990 and earlier FLT/FLHT Ultra model motorcycles are experiencing these difficulties, install this kit. **You will not be required to obtain prior approval for motorcycles out of warranty.** The installation is fairly complicated, so be sure to read the Instruction Sheet carefully before you begin installation.

Warranty Information

Upon installation of the Brake Lamp Relay Kit (Part No. 77043-91), submit a properly completed Warranty Claim Form, referencing this Service Bulletin M-1017, using Labor Code 5170. You will be credited for 1.5 hours labor on all models, and for dealer net plus 10% for each kit.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	TECHNICIAN NO. 4	RETURN THIS TO
INITIAL HERE									