## SERVICE BULLETIN

HARLEY-DAVIDSON

\*\*COMPANY

\*\*COM

M-1025 May 26,1992

## **BATTERY CASES**


Yuasa has changed their molds to eliminate the sharp bottom edges of their battery cases.

See illustration. Until the new batteries are available, Harley-Davidson suggests that whenever an original equipment or Parts and Accessories battery is removed or replaced for any reason, the sharp bottom edge be

dressed. Use a medium emery paper.

## WARNING

Do not remove battery case material other than at the sharp edge. If material other than the edge is removed, it is possible the battery case could leak fluid.



ROUTING	SERVICE	SALES	PARTS	LEAD	TECHNICIAN	TECHNICIAN	TECHNICIAN	TECHNICIAN	RETURN
	MANAGER	MANAGER	MANAGER	TECHNICIAN	NO. 1	NO. 2	NO. 3	NO.4	THIS TO
INITIAL HERE									