

SERVICE BULLETIN



M-1038

Safety Recall Code 084

November 16, 1993

SPORTSTER FRONT FENDER BOLTS

General

Harley-Davidson has discovered some front fender retention bolts of Sportster family motorcycles manufactured from September 23, 1993 through October 15, 1993 could possibly break. If the bolt(s) break, it could allow the front fender to come in contact with the front tire, possibly making it difficult to maintain control of the vehicle.

As a precautionary measure, Harley-Davidson has elected to initiate a voluntary recall in the interest of motor vehicle safety. Harley-Davidson is shipping 4 new bolts, Part No. 3210A and 4 new nuts, Part No. 7531, as a kit (Part No. 93722), to replace the bolts and nuts currently on these vehicles.

Shipment of kits should begin on or before November 22, 1993. Your total requirement of kits will be shipped to you no charge, transportation paid. If additional kits are needed, please contact your Telemarketing Sales Representative.

Procedure

1. Remove the bolts and nuts from one side.

2. Install the new bolts and new nuts
3. Tighten the bolts to 8-13 ft-lbs torque.
4. Repeat procedure for other side.

Credit Procedure

For each vehicle repaired, completely fill out a Dealer Service Card. Place a "C" in the letter box. Affix your bar coded dealer label to the card in the appropriate box, if using the new style card supplied to the customer with the notification. If using the old style dealer service card, be sure you supply all necessary information, including VIN, your dealer number and dealership name and address.

When Harley-Davidson receives your properly completed Dealer Service Card and the replaced bolts and nuts you will receive 0.3 hr labor time for each vehicle serviced, which includes 0.1 hr administrative time. No credit will be issued for parts because they were sent no charge, transportation paid.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	TECHNICIAN NO. 4	RETURN THIS TO:
INITIAL HERE									

1993 Harley-Davidson® Inc.



S
O
L
D

NAME _____

ADDRESS _____

T
O

CITY/STATE/ZIP _____

S H I P NAME _____
ADDRESS **SAME** _____
T O C I T Y / S T A T E / Z I P _____

DEALER ORDER
ORDER DATE
DEALER NO.
ORDER TYPE
D-W
WARRANTY CLAIM NO.

FOR OFFICE USE ONLY
ACCT. 173-776.2
FRT. ACCT. 173-776.3

[illegible]

ALL ORDERS SUBJECT TO ACCEPTANCE AT MILWAUKEE. WI 53201

All goods covered by this order, including goods back-ordered, will be billed at prices current at the time of shipment. Goods are purchased for resale and delivery is made to purchaser F.O.B. factory, Milwaukee, Wisconsin or other point of origin. If accepted, this order is deemed to subject to availability of goods to delivery to purchaser. Any delay in shipment shall not relieve purchaser of responsibility for his acceptance of order and seller shall not be liable for any loss or damage due to delay in shipment of goods to deliver. Any request for cancellation of this order or any part thereof must be received by seller prior to the date of shipment, and in case of reshipment or return of goods to seller, purchaser shall pay the entire cost connected therewith, plus two (2) or twenty-five (25) percent of selling price, as determined by Company policy from time to time. Purchaser will be responsible for collection and payment of all Federal, State and local taxes that apply on the sale of goods.

PLEASE USE PART NUMBERS
DO NOT USE FOR
CORRESPONDENCE

F-1040

PRINTED
IN U.S.A.