SERVICE BULLETIN



M-1166

January 25, 2005

2006 VRSCR INITIAL CARE PROGRAM

General

The purpose of this bulletin is to provide information on the Initial care Program for 2006 VRSCR Model Year motorcycles.

As part of the introduction of the 2006 VRSCR, Technical Service is providing the VRSCR Initial Care Program. Key components in the program are:

- VRSCR Initial Care Phone Line (414) 343-8357: allows direct access for technical support and warranty pre-approval decisions.
- Minimal parts protected, allowing dealers to stock an inventory of repair parts.

- Warranty Pre-Authorization from VRSCR Technical Service is required for specific components in Table 1. This allows Harley-Davidson to monitor initial repair trends on significant components.
- Emergency weekend or holiday repairs can be completed by the dealer only if customer satisfaction is at stake, but will still require contacting VRSCR Initial Care on the following weekday for review and authorization.
- The VRSCR Initial Care Program has an intended life span of Product Launch through August-1-2005. It will be reviewed at that time and extended if necessary.

| Description Part Number | | Description | Part Number | |
|-------------------------|----------|----------------------------------|--------------|--|
| Clutch Master Cylinder | 38744-06 | Lower Triple Clamp | 46781-06 | |
| Brake Disc, Rear | 41667-06 | Frame Assembly, Upper | *47915-06XXX | |
| Reservoir Hose | 41669-06 | Seatpan Assembly | 47923-06 | |
| Caliper, RH Front | 44505-06 | Frame Weldment, LH Lower | *47984-06XXX | |
| Caliper, LH Front | 44506-06 | Frame Weldment, RH Lower | *47986-06XXX | |
| Master Cylinder, Front | 44551-06 | Aux. Volume Chrome/Dom | 65206-06 | |
| Brake Disc, Front | 44553-06 | Aux. Vol. Cat, Chrome HDI | 65211-06 | |
| Caliper, Rear | 44557-06 | Banjo Bolt, Rear Brake Switch | 72025-06 | |
| Fork, LH Front | 46774-06 | Fuel Tank | 61384-06 | |
| Fork, RH Front | 46775-06 | Fuel Module | 75146-06 | |
| Upper Triple Clamp | 46780-06 | | | |

Table 1-1. Components Requiring Pre-Authorization for Replacement Under Warranty

| IMPORTANT NOTE In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service. | | | | | | | | | | | |
|--|--------------------|------------------|------------------|--------------------|--------------------|---------------------|---------------------|---------------------|-------------------|--|--|
| ROUTING | SERVICE MANAGER | SALES MANAGER | PARTS MANAGER | LEAD TECHNICIAN | TECHNICIAN NO.1 | TECHNICIAN NO. 2 | TECHNICIAN NO. 3 | TECHNICIAN NO. 4 | RETURN THIS TO | | |
| INITIAL HERE | | | | | | | | | | | |
| ©2005 HARLEY-DAVIDSON MOTOR COMPANY | | | | | | | | | | | |