SERVICE BULLETIN

M-1239 January 8, 2009



CALIBRATION UPGRADE FOR 2008 TOURING MODELS WITH ABS

Purpose

A recent refinement to the ABS (Anti-Lock Brake System) calibration of 2008 Touring model motorcycles adds compatibility with Michelin replacement tires offered by Parts & Accessories, accommodates police usage performance requirements and permits re-use of Hydraulic Control Unit (HCU) if Electrical Control Unit (ECU) replacement is required.

Since Harley-Davidson is committed to continuous improvement, an ABS calibration change was recently incorporated into all ABS equipped Touring model motorcycles on the production line.

Furthermore, in the interest of promoting customer satisfaction, Harley-Davidson has decided to offer a current production equivalent ABS calibration upgrade at no charge to all owners of 2008 Touring model motorcycles. This offer includes stock production, Police and CVO motorcycles. This calibration upgrade offer is valid from now to the end of the motorcycle's warranty period.

Motorcycles Affected

All 2008 model year Touring model motorcycles equipped with ABS.

Required Dealer Action

If customer requests the ABS calibration update, proceed with the following steps:

- Connect Digital Technician to the vehicle. If the displayed ECU calibration is 32836-08, then the ECU should be reflashed to the 31854-08 calibration.
- Complete ABS Service within Digital Technician after performing reflash.

Credit Procedure

NOTE

Warranty coverage for calibration updates ends with normal vehicle warranty.

Complete a warranty claim referencing Service Bulletin M-1239. Fill in the rest of the claim as follows:

ENTRY FIELD	ENTER				
Claim Type	MC/DEM				
Event Problem Part No.	32836-08/DT				
Quantity	Leave Blank				
Primary Labor Code*	2677				
Time	0.2 Hours				
Customer Concern Code*	9203				
Condition Code*	9110				
* These codes may need to be downloaded into your					

^{*} These codes may need to be downloaded into your system

IMPORTANT NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	LEAD TECHNICIAN	WARRANTY PROCESS MANAGER	TECHNICIAN NO.1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO	
INITIAL HERE										
©2009 H-D										

M-1239 1 of 1