# SERVICE BULLETIN



M1521 2021-02-09

### M1521: 2021 FLHXSE - OUTER FAIRING SHIPPING SPACERS

## **Purpose for Service Bulletin**

This bulletin informs dealers that 2021 FLHXSE painted in Great White Pearl may arrive at the dealership with foam spacers in between the inner and outer fairings.

### **Motorcycles Affected**

2021 FLHXSE

#### **Markets Affected**

All markets are affected.

#### **Required Dealer Action**

See Figure 1. Remove and discard the foam shipping spacers when installing the windshield per the 2021 Predelivery Inspection (PDI) manual.



Figure 1. Fairing Spacers

,	in the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is prought into your dealership for either maintenance of sec									
	ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
	INITIAL HERE									