

TECH TIPS #57

December Issue 2003

100 th Anniversary Sterling Silver, Black and Gunmetal Painted Parts Clarification - January 06, 2003.....	1
Vehicle Cranks but Won't Start - January 13, 2003.....	2
2000 and 2001 Softail Deuce Swingarm/Frame Contact - January 20, 2003	3
Warranty Information - January 27, 2003	4
Digital Technician Phase 8 DVD Update - February 03, 2003.....	5
2003 Radio - February 17, 2003.....	6
HTCC Forged Stroker Piston Ring Identification - February 23, 2003.....	7
Digital Technician - Buell B9SL Model - March 10, 2003.....	8
Injected Twin Cam High Temperature Idle - March 17, 2003	9
Twin Cam 88 and 88B Sprocket Bearing and Crankcase Part Information - March 21, 2003.....	10
EFI Race Tuner Kit Changes - March 24, 2003	12
Warranty Information - March 31, 2003.....	13
Setting Idle Speed with Digital Technician - April 07, 2003.....	15
Saddlebags & Sidecover Damage on Touring Models - May 05, 2003	16
Muffler Recommendations - July 07, 2003.....	17
Accessory Fitment Questions - July 14, 2003.....	18
Twin Cam Breather Assemblies - July 28, 2003	19
Adjustable Rider Backrest Kits For Touring Models - August 04, 2003.....	20
New Radio Changes Affect 1998 - 2003 Models - August 11, 2003.....	21
P&A Compass Tips - September 08, 2003.....	22
Painted Parts Orders - September 22, 2003.....	24
Buell Speed Sensor - September 29, 2003.....	25
P&A Compass Tips - October 06, 2003.....	26
ECM and ICM Issues - October 13, 2003.....	28
TSM/TSSM Information - October 20, 2003	29
Engine Noise and Vibration Complaints - October 29	30
V-Rod Cooling System Issues - November 3, 2003.....	31
Accessory Power - 2004.....	32
Recent Changes - November 10, 2003.....	33
Piston Fitment - November 24, 2003	34
Passing Lamp Changes - North American Vehicles Only - December 01, 2003.....	35
Saddlebag Location on 2004 Models - December 8, 2003	36
Ultra Sidecar Sound System.....	38
Primary Housing To Crankcase/Transmission Interface - December 22, 2003.....	39