

May 10, 2004

2004 XL Rear Caliper

When removing the rear caliper pin bolt, part number 44184-04, and raising the caliper, the brake pads will rotate and come out of the retention clip. During reassembly you must be certain to visually check that the brake pads are properly reinserted into the retention clip. If the pads are not positioned properly you will cross thread the pin bolt in the aluminum caliper during reassembly.

A cross-threaded caliper pin bolt may permit the caliper to rock side to side on the bracket when the brake is applied causing drag and noise.

