

January 17, 2005

Screamin' Eagle® Pro EFI Race Tuner

Please be aware that the 1450 stage one downloads for Softail motorcycles with a calibration ID of 32830-01 will need to have the ECM reflashed with a stock calibration from Digital Technician to allow the EFI Race Tuner to start the programming process correctly. If the motorcycle has this calibration and is not reflashed to a stock calibration you will receive error messages when trying to program the ECM.