

March 22, 2005

Twin Cam Piston Identification Markings

There has been a running change to the identification markings on the top of the pistons for original equipment and replacement Twin Cam pistons. The piston markings will all reflect the engine displacement they are intended to be used in. One example would be the stroker piston. It was labeled "103" or "103 BETA" now it will be "1690A" or "1690B" depending on if it is a balanced or non-balanced motor. This will make the piston markings consistent and also help on the assembly line.