

April 4, 2005

Softail Flywheel Balancer Sprocket

There was a production change to the balancer sprocket that is used on the Twin Cam Softail flywheel assemblies. As a result of this change the balancer shaft sprocket alignment tool, part #HD-44064, will not fit over the new gear. The tool has been changed and the part number is HD-44064A. If you have the capability to machine the tool the dimensions are listed below, if not you will need to order the revised tool.

