

May 9, 2005

2005 XL Model Wire Harness Elbow

If you remove the RH wire harness elbow, part # 73205-05, it is recommended to install washer # 6859M on the mounting bolt when reinstalling the elbow. This is to prevent future damage to the elbow's mounting hole. This washer is being installed in production as of February 27, 2005.

