

October 3, 2005

XL Stator plug connector

Starting in mid-September of 2005 there will be a retainer for the A/C connector (46A and 46B) between the stator and the Voltage regulator installed on all XL models. This new retainer adds stability and retention to the connector and will help prevent separation of the two halves of the connector. The attached photo shows the connector in white for visibility, the production part will be black in color, as shown in the lower photo. The service part number is 29984 - 06 and can be installed on all XL models using this style connector for additional security of this critical connection.

