

TT221 – November 28, 2005

2006 HDI Dyna Model O2 Sensor Plugs

The HDI Dyna Models use a plug on the exhaust pipes rather than an O2 sensor that is used in the Domestic market. If the plug (part # 66054-06) comes loose or has to be replaced you will want to install a seal ring (part # 27714-06) on the plug when you reinstall it. This plug should be torqued to 29-44 ft. lbs.