

### 2006 Dyna neutral switch part number

There has been a change to the neutral switch due to the transmission recall. The original switch was part # 33913-06. This switch should not be ordered any longer. Any motorcycle that would need that switch would fall under recall code 0124 found in Service Bulletin M-1183 and should have the recall performed. This switch is not compatible with the new shift drum being installed under the recall. The new switch is part # 33926-06. This is the replacement switch for current production and bikes that have had the recall completed.

