

TT292 – February 19, 2007

**2004 & Later Sportster Frames**

Recently H-D has developed a tool to replace the jiffy stand spring tab on the frame, eliminating the need to replace the frame for this condition. The condition of the frame and nature of the damage must be evaluated by Technical Service to determine the appropriate repair.

If a bike missing the spring tab comes to your dealership, contact Technical Service to coordinate the loan and use of the tool designed to flatten, drill and thread the frame to accept the replacement anchor. When you receive the tool it will come with instructions on how to perform this repair, or you can print I-sheet J04311 from h-dnet.

**NOTE:** This tool can only be used on 2004 and later XL's and is not available for purchase.

If frame replacement is required, please be aware that the 2004-2006 XL frame part number is 48878-04 and the 2007 XL frame is part number 48882-07.