

Sportster Rear Brake Switch Wiring

2004-2006 Sportster printed service literatures, including Digital Technician service manuals, contain inaccurate rear brake switch connections in the wiring diagrams.

INCORRECT

The O/W wire is incorrectly shown connected to the same terminal as R/Y wire in current publications.

CORRECT

Please correct all publications to depict two R/Y wires connected to one terminal and one O/W wire connected to the other terminal.

