



TT392: VRSCF Protective Tape Removal

September 12, 2008



Chassis

APPLIES TO	SYMPTOMS
2009 Brilliant Silver VRSCF Models	<ul style="list-style-type: none">• Cosmetic Information

VRSCF Protective Tape Removal

The protective tape used on some of the earlier production Brilliant Silver V-Rod Muscle models has an adhesive that may be difficult to remove or result in paint damage when removing it at set-up.

To aid in removal, we suggest using "warm" heat, such as a hair dryer set on high or heat gun set on low.

A new tape will be used on all production Silver V-Rods effective September 15, 2008 and should eliminate the need for this extra set-up step.