



# TT419: Buell Side Fairing Kit Installation

November 18, 2009



**Chassis**

APPLIES TO	SYMPTOMS
2008-2010 1125 Models	<ul style="list-style-type: none"><li>• Part Availability, Installation or Fitment Updates</li><li>• Literature Updates or Corrections</li></ul>

Instruction sheet -J05029 (dated 11/06/09) has been updated to include the following statement:

- 15. Make a final check for clearance between the right side fairing and the exhaust pipes. If they are touching the exhaust you will need to loosen and adjust the lower fairing brackets to gain a minimum of 1/4 inch of clearance.

Conditions have been reported where contact may occur between the fairing and head pipe if the proper clearance is not maintained. The resulting damage would be due to improper installation and would not be warrantable.