Parts & Accessories Bulletin

February 6, 1987



P&A #329

CAST WHEEL ASSEMBLY PART NUMBER 43299-87

Due to a change in vendor the above rear, black, 16 spoke Cast Wheel Assembly for 1986 FLHTC, FLHT, FLHTP models, will no longer be offered.

It will be replaced by Part Number 43299-87, Rear, 10 spoke, Cast Wheel Assembly.

Pricing on the New wheel is as follows:

Suggested List: \$233.31 Dealer Net: \$151.60

Thank you!

Parts & Accessories

