SERVICE HARLEY-DAVIDSON

No. 611

May 20, 1970

BULLETIN

CARBURETOR JET / ELECTRA GLIDE

The main fuel jet of the 74 OHV FL and FLH carburetor has been changed from size No. 53 (part No. 27616-66) to No. 59 (part No. 27619-66) starting on February 23, 1970, with VIN 2A 20684 HO.

The change to the No. 59 jet was made to provide best mixture for standard and optional exhaust systems under most operating conditions, because service experience had shown some cases of lean operation at high speed with the No. 53 jet.

If a tendency toward high speed leanness is noted on 1969 and 1970 Electra Glide motorcycles below VIN 2A 20684 H0, the No. 59 jet is recommended.

HARLEY-DAVIDSON MOTOR CO., INC.