

SERVICE BULLETIN



M-1058

April 26, 1996

VOLUME CONTROL REPLACEMENT SWITCH Part No. 71593-96

Purpose

Harley-Davidson has determined that the replacement volume control switch, Part. No. 71593-96, must be installed differently on FLT Ultra and FLT Classic models.

Required Dealer Action

INSTALLING REPLACEMENT SWITCH ON FLT ULTRA MODELS:

To install replacement switch on Ultra models, follow the replacement procedures in the applicable FLT service manual.

INSTALLING REPLACEMENT SWITCH ON FLT CLASSIC MODELS:

To install replacement switch on Classic models, follow the replacement procedures in the applicable FLT service manual with the following exceptions:

1. Under GENERAL REPAIR PROCEDURES, instead of matching replacement switch wire colors to existing wire colors, splice wire colors as shown in table below.

Replacement Volume Switch Wire Color	Existing Wire Colors
GY/GN	GN/BE
PK/W	PK/W
BN/BK	BN/BK
GN/BE	GY/GN

2. Fit the new switch into the housing cavity with the gray/green wire ON THE BOTTOM. If the gray/green wire is topside, as described in Ultra model instructions, the switch knob with fit on the switch post upside down.

NOTE

In addition to this Service Bulletin, all replacement switches packaged after April 26, 1996 will have these instructions included.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO.1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	TECHNICIAN NO. 4	RETURN THIS TO
INITIAL HERE									