

**TSM/TSSM Information**

All 2004 H-D motorcycles require -01**C** or -00**C** modules. These **C** modules will retrofit to earlier vehicles.

The -01B, -00B and earlier modules will not function properly on 2004 models because they lack odometer display capability and the shorter time to storage mode. If you have any inventory of these earlier modules they can still be used on pre -04 vehicles.