

Adjustable Rider Backrest Kits For Touring Models

There are two repair kits available for rider backrests on 1997 and later FL Touring models equipped with the following rider backrest seats:

52468-01

52473-01

52474-01

52475-01

52476-01

52479-01, Backrest Adjustment Handle Kit, replaces the release handle and cable assembly*. This would cure complaints of a limp handle because of a missing cable end(s).

53047-01, FL Adjustable Rider Backrest Repair Kit, is the backrest pivot ** which includes the spring steel tab. This would cure a pivot tab damaged by inserting the backrest in the wrong opening. This kit is also referenced in P&A Bulletin 735 dated 12/12/02.

There are no repair kits available for the Softail versions of seats with rider backrest.

* refer to I Sheet J02026

** refer to I Sheet J02156