

TT285 – January 19, 2007

## Recall 0127 Information


This Tech Tip will help you identify the correct part number of the handlebars as requested in the Credit Procedure on page 2 of Service Bulletin M-1201

### 2007 FXDWG

If the motorcycle that is having the recall performed is a 2007 FXDWG use condition code 9983 (part number 59782-07) this handlebar should have no crimp in the bar behind the brake master cylinder.

### 2006 FXDWG

If the handlebar has a "single dent" crimp (left in the photo below) the handlebar is a 59782-06 - use code 9981. If the handlebar has a "two dent" crimp (right in the photo below) the handlebar is a 59782-06A - use code 9982. Please refer to the pictures below.



Part number 59782-06 (use code 9981)

Part number 59782-06A (use code 9982)