

TT286 – January 24, 2007

## **Twin Cam Gasket Kits and Main Bearings**

### Gasket Kits

Please be aware that gasket kits 17052-99B & 17053-99B do not include the cylinder head gasket or cylinder base o-ring for the 2007 CVO (110") Models. You will need to order these separately for these models. The 110" cylinder head gasket is part # 16801-07 and the cylinder base o-ring is part # 10956. Please make a note in your Parts Manuals and inform your Parts Personnel of this also.

### Main Bearings

Please be aware that H-D recommends the replacement of the crankcases flywheel main bearings when installing any new flywheel assembly. This initiative should be performed during any engine related service that includes flywheel replacement or flywheel performance upgrades.